Owner Name and Address: Bob Burns PO Box 190 Babb MT 59411 Phone: (406) 732-4532

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1802264	Lariat Motel	US Highway 89	Babb	59411	(406) 732-4532

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use		4/25/1982 24 / No	Diesel 4,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	ABCDEFGHIJK® B DEFGHIJK®	No No No No
2 / 02 Currently in Use		4/25/1982 24 / No	Gasoline 4,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	(ABCDEFGH)JK• B DEFGH)JK•	No No No No
3 / 03 Currently in Use		4/25/1985 21 / No	Gasoline 10,000	Asphalt Coated or Bare Steel None	Galvanized Steel None	Not Listed	(ABCDEFGHIJK) B DEFGHIJK)	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 21

Owner Name and Address: Thronsons Store PO Box 169 Babb MT 59411 Phone: (406) 732-5530

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1803871	Thronsons Store	US Highway 89	Babb	59411	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 07 Currently in Use	4401	12/31/1989 16 / No	Gasoline 7,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCDEF®HIJKL • • EFGHIJKL	Yes Yes Yes Yes
2 / 08 Currently in Use	4402	12/31/1989 16 / No	Gasoline 3,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEF@H)J(K)	Yes Yes Yes Yes
3 / 06 Currently in Use	4403	12/31/1989 16 / No	Gasoline 8,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	ABCDEF.H.J.K.L. • • EFGHJ.K.L.	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 21

Owner Name and Address: Browning Public Schools Dist 9 PO Box 610 Browning MT 59417 Phone: (406) 338-2952

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1803868	School Dist 9 Maintenance Complex	Boundry St	Browning	59417	(406) 338-2952

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	4130	11/29/1986 19 / No	Gasoline 8,000	STI-P3 Impressed Current	Galvanized Steel Impressed Current	U.S. Suction	(A	Yes Yes Yes Yes
3 / 03 Currently in Use	4131	11/28/1989 16 / No	Diesel 8,000	Polyethylene Tank Jacket Impressed Current	Galvanized Steel Impressed Current	U.S. Suction	(A	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 21

Owner Name and Address: Hi Noon Petroleum PO Box 7578 Missoula MT 59807 Phone: (406) 532-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1805813	P & M Convenience Store 433	330 W Central Ave	Browning	59417	(406) 338-7615

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	4441	1/3/1997 09 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFOHIJKL) (BCOEFGHIJKL)	Yes Yes Yes Yes
5 / 05 Currently in Use	4442	1/3/1997 09 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
6 / 06 Currently in Use	4443	1/3/1997 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EF●HIJ&L ● EFGHIJ&L</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 4 of 21

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1808677	Town Pump Inc Browning 2	US Highway 89	Browning	59417	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 13 Currently in Use	2467	6/1/1995 11 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABC • E F • H 1 J & L B • E F • H 1 J & L	Yes Yes Yes Yes
2 / 11 Currently in Use	2465	6/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B 0 E F 0 H 1 J K L	Yes Yes Yes Yes
3 / 12 Currently in Use	2466	6/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJ&L B OEFOHIJ&L	Yes Yes Yes Yes
4 / 10 Currently in Use	4888	6/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKU B OEFOHIJKU	Yes Yes Yes Yes
13 / 09 Currently in Use	2463	6/1/1995 11 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes
14 / 14 Currently In Use	4859	8/14/2003 02 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEF H D K L	Yes Yes Yes Yes
15 / 15 Currently In Use	4860	8/14/2003 02 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABC • E F • H 1 J & L B D E F • H 1 J & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 21

Owner Name and Address: Browning Public Schools Dist 9 PO Box 610 Browning MT 59417 Phone: (406) 338-2952

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1812747	School Dist 9 Transportation Dept	829 SW Boundary St	Browning	59417	(406) 338-2952

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 03 Currently in Use	1900	7/1/1992 14 / No	Used Oil 1,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(A • C • E F G H J K L B D E F • H J K L	Yes Yes Yes Yes
2 / 01 Currently in Use	1898	7/1/1992 14 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>A • C • E F G H J & L • • E F G H J & L </pre>	Yes Yes Yes Yes
3 / 02 Currently in Use	1899	7/1/1992 14 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	A • C • E F G H J K L • • E F G H J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 21

Owner Name and Address: Pat & Violet Schildt PO Box 1777 Browning MT 59417 Phone: (406) 338-7640

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1813768	Glacier Way Convenience Store	Starr School Road & Duck Lake Road	Browning	59417	(406) 338-7163	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	3425	9/25/1996 09 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	3426	9/25/1996 09 / No	Diesel 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEF.H.J.K.L	Yes Yes Yes Yes
3 / 03 Currently in Use	3427	9/25/1996 09 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 21

Owner Name and Address: Cut Bank Airport Authority 2705 Valier Highway Cut Bank MT 59427 Phone: (406) 873-8683

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1800137	Cut Bank Municipal Airport	2705 Valier Highway	Cut Bank	59427	(406) 873-8683

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
8 / 08 Currently In Use	793	11/1/1997 08 / No	Other 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A • • D E F G H J J K L B • E F • H J J K L	Yes Yes Yes Yes
9 / 09 Currently In Use	794	11/1/1997 08 / No	Other 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	A • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 21

Owner Name and Address: Kennys Super Service 401 E Main St Cut Bank MT 59427 Phone: (406) 873-2432

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1800321	Kennys Super Service	401 E Main St	Cut Bank	59427	(406) 873-2432

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	1471 (6/13/1985 21 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIJKL B DEFGHIØKL	Yes Yes Yes Yes
2 / 02 Currently in Use	1472	6/13/1985 21 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	B DEFGHIJKL B DEFGHI•KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 21

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1803417	Town Pump Inc Cut Bank 2	510 W Main St	Cut Bank	59427	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2459	3/1/1993 13 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
2 / 02 Currently in Use	2460	3/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	\(\begin{align*} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Yes Yes Yes Yes
3 / 03 Currently in Use	2461	3/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
4 / 04 Currently in Use	2462	3/1/1993 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJ&L ● ●EFGHIJ&L</pre>	Yes Yes Yes Yes
7 / 07 Currently In Use	4185	5/1/2000 06 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
8 / 08 Currently In Use	4186	5/1/2000 06 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	8 DEF.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 21

Owner Name and Address: Ben Taylor Inc PO Box 810 Shelby MT 59474 Phone: (406) 434-5546

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1804137	Ben Taylor Inc UST	201 BN Industrial Site	Cut Bank	59427	(406) 873-2812

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
16 / S16 Currently In Use	4241	10/29/2000 05 / Ye	Gasoline 34,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJEL B DEFOHIJEL	No Yes Yes Yes
17 / S17 Currently In Use	4242	10/29/2000 05 / Ye	Gasoline 11,700	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJEL B DEFOHIJEL	No Yes Yes Yes
18 / S18 Currently In Use	4243	10/29/2000 05 / Ye	Diesel 12,500	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGH1J&L B DEF@H1JKL	No Yes Yes Yes
19 / S19 Currently In Use	4244	10/29/2000 05 / Ye	Diesel 34,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJ&L) (B DEFOHIJKL)	No Yes Yes Yes
20 / S20 Currently In Use	4245	10/29/2000 05 / Ye	Diesel 12,500	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJ&L) (B DEFOHIJ&L)	No Yes Yes Yes
21 / S21 Currently In Use	4246	10/29/2000 05 / Ye	Diesel 11,700	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJEL B DEFOHIJEL	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 21

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone	
1808693	Town Pump Inc Cut Bank 1	1101 E Main St	_	Cut Bank	59427		-

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4873	1/1/1967 39 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	4874	1/1/1967 39 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHJ&L B DEFOHJJ&L	Yes Yes Yes Yes
3 / 03 Currently in Use	4875	1/1/1967 39 / No	Gasoline 4,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHJ&L B DEFOHJJ&L	Yes Yes Yes Yes
4 / 04 Currently in Use	4876	9/20/1988 17 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC•EF6H1JKL B DEF•H1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 21

Owner Name and Address: Harvest States Coop PO Box 1272 Cut Bank MT 59427 Phone: (406) 873-2081

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1813623	Harvest States Coop Cut Bank	29 N Central Ave	Cut Bank	59427	(406) 873-2081	

TankID/Alt TankID Status	Tag Installed Numbe Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently in Use	5/20/1995 11 / Ye	Hazardous	Unknown None	Bare Steel None	Safe Suction	ABCDEFGHIJOL B DEFGHIOKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 21

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
3709185	Malmstrom AFB T 41	Road 358	Cut Bank	59427	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	293 5/2/1966	Diesel	Epoxy Coated Steel	Bare Steel	U.S. Suction	ABCD0FGHJ)&L	Yes
Currently in Use	40 / No	11,000	Impressed Current	Impressed Current		B D0FGHJJ&L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 21

Owner Name and Address: Simons Petroleum Inc 530 Roosevelt Highway Station PO Box 644 Shelby MT 59474 Phone: (406) 434-2431

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5613775	Simons Bulk Plant Cut Bank Satellite	813 E Railroad St	Cut Bank	59427	(406) 434-2431	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	1928	10/31/1997 08 / Ye	Diesel 12,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes
2 / S2 Currently In Use	1929	10/31/1997 08 / Ye	Gasoline 8,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 15 of 21

Owner Name and Address: Les Baker 301 12th Ave NE Choteau MT 59422 Phone: (406) 466-5923

Sys Fac I Location Name Location Street Address Location City 7 In Location Phone

Sys Fac ILocation NameLocation Street AddressLocation CityZipLocation Phone5614022Site 8090US Highway 2Cut Bank59427

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Temporarily Out of U	-	1/1/1940 66 / No	Diesel 550	Asphalt Coated or Bare Steel None	Bare Steel None	Not Listed	B DEFGHIJKO	No No No No

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 16 of 21

Owner Name and Address: Judy Jones 11 Live Oak Ln Fort Myers FL 33905 Phone: (406) 226-4432

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1803870	Sears Motel & Gift Shop	1023 MT Highway 49 N	East Glacier Park	59434	(406) 226-4432

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 03 Currently in Use	1453	9/28/1990 15 / No	Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • • • G H I J K L B D E F G H I • K L	Yes Yes Yes Yes
3 / 04 Currently in Use	1454	9/1/1990 15 / No	Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 17 of 21

Owner Name and Address: Julie Fortune Development Co LLC PO Box 468 East Glacier Park MT 59434 Phone: (406) 226-5504

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613933	Bear Track Travel Center	20958 US Highway 2	East Glacier Park	59434	(406) 226-5504

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	4068	6/1/1999 07 / Ye	Gasoline 8,000	Unknown Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes
2 / S2 Currently In Use	4069	6/1/1999 07 / Ye	Gasoline 5,000	Unknown Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGHIJEL B DEFOHIJEL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging C Invent	tory Control E Vapor Monit	toring G Interstit, Dbl-Wall Monitor	I SIR	K Deferred	
	,	9		L Not Listed	

Report Generation Date: 7/3/2006 Page 18 of 21

Owner Name and Address: St Mary Enterprise General Delivery Highway 89 Saint Mary MT 59417 Phone: (406) 732-4431

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1801907	St Mary Lodge	Highway 89 St Mary Lake	Saint Mary	59417	(406) 732-4431

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 03 Currently in Use	453	6/1/1990 16 / No	Gasoline 7,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Pressurized	(ABCDEFGHIJK) (B) EFGHIJKL	No No No Yes
2 / 04 Currently in Use	454	6/1/1990 16 / No	Diesel 3,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Pressurized	B	No Yes Yes Yes
3 / 01 Currently in Use	451	6/1/1990 16 / No	Gasoline 15,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	No Yes Yes Yes
4 / 02 Currently in Use	452	6/1/1990 16 / No	Gasoline 15,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled/Non-Corro	Pressurized	(ABCOEFGHIJKL B OEFOHIJKL	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 19 of 21

Owner Name and Address: US Department of Interior Glacier National Park PO Box 128 West Glacier MT 59936 Phone: (406) 888-7870

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1802745	Saint Mary Ranger Station	National Park Service	Saint Mary	59417	(406) 888-7978

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	1221	7/1/1987 19 / No	Gasoline 12,000	STI-P3 None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABC●EF®HIJKL B DEF●HIJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	1222	9/1/1992 13 / No	Diesel 4,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Safe Suction	ABCOEFOHIJKU B DEFGHIOKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 20 of 21

Owner Name and Address: Neal & Kathryn Miller & Rob HC 72 Box 5 Saint Mary MT 59417 Phone: (406) 732-4482

Hiestand

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
1806436	Park Cafe and Grocery Saint Mary	HC 72 Box 5	Saint Mary	59417	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 07 Currently in Use	1382	11/1/1991 14 / No	Diesel 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H I J K L B • E F G H I J K L	Yes Yes Yes Yes
2 / 05 Currently in Use	1380	11/1/1991 14 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGHIJKU B ●●FGHIJKU	Yes Yes Yes Yes
3 / 06 Currently in Use	1381	11/1/1991 14 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC • EFGH J K L B • • FGH J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 21 of 21